

# Intel® Xeon® Processor E7- 8800/4800/2800 Product Families

Specification Update

---

*April 2012*



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

Intel products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

The Intel® Xeon® Processor E7-8800/4800/2800 Product Families may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available upon request.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See [http://www.intel.com/products/processor\\_number](http://www.intel.com/products/processor_number) for details.

64-bit computing on Intel architecture requires a computer system with a processor, chipset, BIOS, operating system, device drivers and applications enabled for Intel® 64 architecture. Performance will vary depending on your hardware and software configurations. Consult with your system vendor for more information.

No computer system can provide absolute security under all conditions. Intel® Trusted Execution Technology (Intel® TXT) requires a computer system with Intel® Virtualization Technology, an Intel TXT-enabled processor, chipset, BIOS, Authenticated Code Modules and an Intel TXT-compatible measured launched environment (MLE). Intel TXT also requires the system to contain a TPM v1.s. For more information, visit <http://www.intel.com/technology/security>

Intel® Virtualization Technology (Intel® VT) requires a computer system with an enabled Intel® processor, BIOS, virtual machine monitor (VMM) and, for some uses, certain computer system software enabled for it. Functionality, performance or other benefits will vary depending on hardware and software configurations and may require a BIOS update. Software applications may not be compatible with all operating systems. Please check with your application vendor.


Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>.

Intel, Xeon, Pentium, Intel Core, and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.


Copyright © 2011-2012, Intel Corporation. All Rights Reserved.



# Contents

---

Revision History .....	5
Preface .....	6
Summary Tables of Changes .....	8
Identification Information .....	12
Intel® Xeon® Processor E7-8800/4800/2800 Product Families BIOS ACM Errata Summary .....	17
Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Errata Summary .....	18
Errata.....	19
Intel Xeon Processor E7-8800/4800/2800 Product Families BIOS ACM Errata .....	30
Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Errata.....	31
Specification Changes.....	32
Specification Clarifications .....	33
Documentation Changes.....	34






# Revision History

---

Revision	Description	Date
-001	Public Release	April 2011
-002	Added BP33 errata	April 2011
-003	Added BP34, BP35 errata	May 2011
-004	Added erratum BP36	July 2011
-005	Added erratum BP37	August 2011
-006	Added erratum BP38	September 2011
-007	Added erratum BP39	October 2011
-008	Added erratum AS2. Updated Tables 2 and 3	December 2011
-009	Added errata BP40 and BP41	February 2012
-010	Added erratum BP42	April 2012



## Preface

---

This document is an update to the specifications contained in the “Affected Documents” table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in “Nomenclature” are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

### Affected Documents

Document Title	Document Number/ Location
<i>Intel® Xeon® Processor E7-8800/4800/2800 Product Families Datasheet Volume 1</i>	325119-001
<i>Intel® Xeon® Processor E7-8800/4800/2800 Product Families Datasheet Volume 2</i>	325120-001

### Related Documents

Document Title	Document Number/ Location
<i>AP-485, Intel® Processor Identification and the CPUID Instruction</i>	<a href="http://www.intel.com/design/processor/aplnots/241618.htm">http://www.intel.com/design/processor/aplnots/241618.htm</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual</i> <ul style="list-style-type: none"><li>• Volume 1: Basic Architecture</li><li>• Volume 2A: Instruction Set Reference Manual A-M</li><li>• Volume 2B: Instruction Set Reference Manual N-Z</li><li>• Volume 3A: System Programming Guide</li><li>• Volume 3B: System Programming Guide</li></ul>	<a href="http://www.intel.com/products/processor/manuals/index.htm">http://www.intel.com/products/processor/manuals/index.htm</a>
<i>Intel® 64 and IA-32 Intel Architecture Optimization Reference Manual</i>	<a href="http://www.intel.com/products/processor/manuals/index.htm">http://www.intel.com/products/processor/manuals/index.htm</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual Documentation Changes</i>	<a href="http://www.intel.com/design/processor/specupdt/252046.htm">http://www.intel.com/design/processor/specupdt/252046.htm</a>



## Nomenclature

**Errata** are design defects or errors. These may cause the Intel® Xeon® Processor E7-8800/4800/2800 Product Families behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.


**S-Spec Number** is a five-digit code used to identify products. Products are differentiated by their unique characteristics, for example, core speed, L2 cache size, package type, etc. as described in the processor identification information table. Read all notes associated with each S-Spec number.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

**Note:** Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, and so forth).



# Summary Tables of Changes

---

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the Intel® Xeon® Processor E7-8800/4800/2800 Product Families. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

## Codes Used in Summary Tables

### Stepping

- X: Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
- (No mark)  
or (Blank box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

### Page

- (Page): Page location of item in this document.

### Status

- Doc: Document change or update will be implemented.
- Plan Fix: This erratum may be fixed in a future stepping of the product.
- Fixed: This erratum has been previously fixed.
- No Fix: There are no plans to fix this erratum.

### Row

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Each Specification Update item is prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:



## Errata Table (Sheet 1 of 2)

Number	Stepping	Status	Description
	A-2		
BP1	X	No Fix	Intel® Interconnect BIST (Intel® IBIST) Does Not Work in Intel® QuickPath Interconnect (Intel® QPI) in Slow Mode
BP2	X	No Fix	Retraining Parameter Negotiation is Not Implemented for Intel QPI
BP3	X	No Fix	Intel® IBIST Slave Ignores Loop Count Values Sent by Master on Intel® QPI
BP4	X	No Fix	System Hangs when Skipping Stop Req2 and Start Req1 Messages in Quiesce/Lock Sequence
BP5	X	No Fix	Integrated Memory Controller Signals Spurious CMCI when Home Agent Failover Count Saturation Occurs
BP6	X	No Fix	Memory Controller Does Not Set S Bit for Uncorrectable Error Followed by Software Recoverable Error
BP7	X	No Fix	MCI_STATUS S Bit Not Set for LLC Software Recoverable Errors
BP8	X	No Fix	Correctable SB CRC Error May be Propagated to an Uncorrected ECC Error
BP9	X	No Fix	Memory Controller Patrol Scrub Ceases to Function with CRC Errors and the IMT31 Reclaim Feature Enabled
BP10	X	No Fix	Electrically Idle Intel SMI and Intel QPI Lanes May Deliver Data that May Look Like Deskew Headers
BP11	X	No Fix	A Sequence of Instruction Fetches and Snoops to Locked Cache Lines May Cause Processor to Hang
BP12	X	No Fix	Writing to Unimplemented Bits of UU_CR_U_MSR_PMON_EVNT_SEL MSR does Not Result in #GP Fault
BP13	X	No Fix	Mixed Rank Size Memory Configurations May Cause a Missing Refresh Event
BP14	X	No Fix	Mirror Slave May Deliver Incorrect Data when a Read to the Mirror Master Completes Before the Write-back from the IOH
BP15	X	No Fix	UU_CR_U_MSR_PMON_GLOL_OVF_CTL MSR Does Not Follow RW1C Access Method
BP16	X	No Fix	HNID Field is Incorrect for CMP Messages From PrefetchHint
BP17	X	No Fix	Page Fault May Occur When Logical Processor Transitions From C6 State to C0 State
BP18	X	No Fix	In DAS Enabled Mode a System Hang May Occur During Memory Intensive Workloads
BP19	X	No Fix	Bit [8] of IA32_APIC_BASE register Inadvertently Set to 1 for Core 9
BP20	X	No Fix	Quad Rank DIMMs With CKE Low Enabled in Open/Adaptive Page Mode May Return Incorrect Data
BP21	X	No Fix	System Configuration Controller Misaligned Error May Result in a System Hang
BP22	X	No Fix	Recoverable Errors Signaled From Intel QPI or Intel SMI Port to the System Configuration Controller May Get Lost if the Ports are Disabled
BP23	X	No Fix	Executing The WAKEUP Leaf of The GETSEC Instruction Multiple Times May Lead to a Machine Check Error
BP24	X	No Fix	CKE-Lo Feature Can Not be Disabled When Memory Controller Transactions are Active




## Errata Table (Sheet 2 of 2)

Number	Stepping	Status	Description
	A-2		
BP25	X	No Fix	Executing The Intel TXT GETSEC SENTER Instruction Leaf May Lead to a Machine Check Error
BP26	X	No Fix	Task Switch to a TSS With an Inaccessible LDTR Descriptor May Cause Unexpected Faults
BP27	X	No Fix	An Intel QPI Link Layer Retry Quickly Followed by an Intel QPI Physical Layer Reset May Cause an MCE
BP28	X	No Fix	LLC Arrays May have Incorrect Values after Warm Reset when Memory BIST is Disabled
BP29	X	No Fix	VM Entries that Return from SMM May Incorrectly Write to the SMRR Protected Region
BP30	X	No fix	System Quiesce Events Initiated While Power Events are In Progress May Cause System Hangs
BP31	X	No Fix	Uncorrected Memory Error Detected by a Memory Patrol Scrub With SMI Generated by Other Memory Controllers May Cause MCE/System Management Interrupt Race Condition
BP32	X	No Fix	Broken trace to either the P or the N lane of the Intel SMI forwarded clock differential pair may result in loss of forwarded clock but not always lead to clock lane failover.
BP33	X	No Fix	Package C3/C6 with Memory Self-refresh Enabled May Cause False Error Logging
BP34	X	No Fix	Performance Monitor WOKEN Event May Under Count
BP35	X	No Fix	PECI Command Average Temperature Read does not report correct Temperature
BP36	X	No Fix	QPI Initialization May Cause a CATERR During Power-on Reset
BP37	X	No Fix	EOI Transaction May Not be Sent if Software Enters Core C6 During an Interrupt Service Routine
BP38	X	No Fix	A First Level Data Cache Parity Error May Result in Unexpected Behavior
BP39	X	No Fix	An Unexpected Page Fault or EPT Violation May Occur After Another Logical Processor Creates a Valid Translation for a Page
BP40	X	No Fix	A Page Fault May Not be Generated When the PS bit is set to "1" in a PML4E or PDPTE
BP41	X	No Fix	IO_SMI Indication in SMRAM State Save Area May be Set Incorrectly
BP42	X	No Fix	Writing an Illegal Vector to the IA32_X2APIC_SELF_IPI MSR Will Hang the Processor

## Specification Changes

Number	SPECIFICATION CHANGES
	None for this revision of this specification update.



## Specification Clarifications

Number	SPECIFICATION CLARIFICATIONS
	None for this revision of this specification update.

## Document Changes

Number	DOCUMENT CHANGES
	None for this revision of this specification update.



# Identification Information

## Component Identification via Programming Interface

The Intel® Xeon® Processor E7-8800/4800/2800 Product Families stepping can be identified by the following register contents:


Reserved	Extended Family <sup>1</sup>	Extended Model <sup>2</sup>	Reserved	Processor Type <sup>3</sup>	Family Code <sup>4</sup>	Model Number <sup>5</sup>	Stepping ID <sup>6</sup>
31:28	27:20	19:16	15:14	13:12	11:8	7:4	3:0
	00000000b	0010b		00b	0110	1111b	0000b

**Note:**

1. The Extended Family, bits [27:20] are used in conjunction with the Family Code, specified in bits [11:8], to indicate whether the processor belongs to the Intel386™, Intel486™, Pentium®, Pentium® Pro, Pentium® 4, Intel® Core™ processor family or Intel® Core™ i7 family.
2. The Extended Model, bits [19:16] in conjunction with the Model Number, specified in bits [7:4], are used to identify the model of the processor within the processor's family.
3. The Processor Type, specified in bits [13:12] indicates whether the processor is an original OEM processor, an OverDrive processor, or a dual processor (capable of being used in a dual processor system).
4. The Family Code corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
5. The Model Number corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
6. The Stepping ID in bits [3:0] indicates the revision number of that model. See [Table 1](#) for the processor stepping ID number in the CPUID information.

When EAX is initialized to a value of '1', the CPUID instruction returns the *Extended Family, Extended Model, Processor Type, Family Code, Model Number and Stepping ID* value in the EAX register. Note that the EDX processor signature value after reset is equivalent to the processor signature output value in the EAX register.


Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register.



## Component Marking Information

Intel® Xeon® Processor E7-8800/4800/2800 Product Families can be identified by the following component markings:

**Figure 1. Processor Top-Side Marking (Example)**



**Table 1. Intel® Xeon® Processor E7-8800/4800/2800 Product Families Identification**

S-Spec Number	Stepping	CPUID	Core Frequency (GHz) / Intel® QuickPath Interconnect (GT/s) / Intel® SMI (GT/s)	Number of Cores	Cache Size (MB)	Series
SLC3E	A-2	000206F2h	2.4 GHz/6.4 GT/s/6.4 GT/s	10	30 MB	E7-8870
SLC3T	A-2	000206F2h	2.4 GHz/6.4 GT/s/6.4 GT/s	10	30 MB	E7-4870
SLC3U	A-2	000206F2h	2.4 GHz/6.4 GT/s/6.4 GT/s	10	30 MB	E7-2870
SLC3F	A-2	000206F2h	2.26 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-8860
SLC3S	A-2	000206F2h	2.26 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-4860
SLC3H	A-2	000206F2h	2.26 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-2860
SLC3D	A-2	000206F2h	2.0 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-8850
SLC3V	A-2	000206F2h	2.0 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-4850
SLC3W	A-2	000206F2h	2.0 GHz/6.4 GT/s/6.4 GT/s	10	24 MB	E7-2850
SLC3K	A-2	000206F2h	2.13 GHz/6.4 GT/s/6.4 GT/s	8	24 MB	E7-8830
SLC3Q	A-2	000206F2h	2.13 GHz/6.4 GT/s/6.4 GT/s	8	24 MB	E7-4830
SLC3J	A-2	000206F2h	2.13 GHz/6.4 GT/s/6.4 GT/s	8	24 MB	E7-2830
SLC3P	A-2	000206F2h	2.13 GHz/6.4 GT/s/6.4 GT/s	10	30 MB	E7-8867L
SLC3N	A-2	000206F2h	2.66 GHz/6.4 GT/s/6.4 GT/s	8	24 MB	E7-8837
SLC3M	A-2	000206F2h	1.73 GHz/4.8 GT/s/4.8 GT/s	6	18 MB	E7-2803
SLC3G	A-2	000206F2h	2.0 GHz/5.86 GT/s/5.86 GT/s	8	18 MB	E7-4820
SLC3R	A-2	000206F2h	2.0 GHz/5.86 GT/s/5.86 GT/s	8	18 MB	E7-2820
SLC3L	A-2	000206F2h	1.86 GHz/4.8 GT/s/4.8 GT/s	6	18 MB	E7-4807



## Mixing Processor Within MP Platforms


Intel supports multi-processor (MP) configurations consisting of processors:

1. From the same power optimization segment
2. That support the same maximum Intel® QuickPath Interconnect (Intel® QPI) and DDR3 memory speeds.
3. That share symmetry across physical packages with respect to the number of logical processors per package, number of cores per package, number of Intel QPI interfaces, and cache topology.
4. That have identical Extended Family, Extended Model, Processor Type, Family Code and Model Number as indicated by the function 1 of the CPUID instruction.

**Note:** Connected processors must operate with the same Intel QPI and core frequency.

While Intel does nothing to prevent processors from operating together, some combinations may not be supported due to limited validation, which may result in uncharacterized errata. Coupling this fact with the large number of Intel® Xeon® Processor E7-8800/4800/2800 Product Families attributes, the following population rules and stepping matrix have been developed to clearly define supported configurations.

1. Processors must be of the same power-optimization segment. This insures processors include the same maximum Intel QPI and cache sizes.
2. Processors must operate at the same core frequency. Note: Processors within the same power-optimization segment supporting different maximum core frequencies (for example, a 2.26 GHz / 130 W and 2.00 GHz / 130 W) can be operated within a system. However, both must operated at the highest frequency rating commonly supported. Mixing components operating at different internal clock frequencies is not supported and will not be validated by Intel.
3. Processors must share symmetry across physical packages with respect to the number of logical processors per package, number of Intel QPI Interconnect interfaces, and cache topology.
4. Mixing dissimilar steppings is only supported with processors that have identical Extended Family, Extended Model, Processor type, Family Code and Model Number as indicated by the function 1 of the CPUID instruction. Mixing processors of different steppings but the same model (as per CPUID instruction) is supported. Details regarding the CPUID instruction are provided in the *AP-487, Intel® Processor Identification and the CPUID Instruction* application note and *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A*.
5. After AND'ing the feature flag and extended feature flag from the installed processors, any processor whose set of feature flags exactly matches the AND'ed feature flags can be selected by the BIOS as the BSP. If no processor exactly matches the AND'ed feature flag values, then the processors with the numerically lower CPUID should be selected as the BSP.
6. Intel requires that the processor microcode update be loaded on each processor operating within the system. Any processor that does not have the proper microcode update loaded is considered by Intel to be operating out of specification.



7. The workarounds identified in this, and subsequent specification updates, must properly applied to each processor in the system. Certain errata are specific to the multiprocessor environment. Errata for all processor steppings will affect system performance if not properly worked around.
8. Customers are fully responsible for the validation of their system configurations.



## Intel® Trusted Execution Technology Authenticated Control Modules

Platforms supporting Intel® Trusted Execution Technology (Intel® TXT) must ship with authenticated control modules, software binaries used to establish a root of trust.

BIOS launches the BIOS ACM (authenticated control module) to establish a static root of trust at power-on. The measured launch environment launches the SINIT ACM to establish a dynamic root of trust at MLE (Measured Launch Event) launch.

**Table 2. Intel® Xeon® Processor E7-8800/4800/2800 Product Families BIOS ACM Releases**

Version	Release Date	Stepping	Signature
BIOS ACM 1.0	11/2010	A-2	Production
BIOS ACM 1.1	3/2011	A-2	Production
BIOS ACM 1.2	10/2011	A-2	Production

**Table 3. Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Releases**

Version	Release Date	Stepping	Signature
SINIT ACM 1.0	3/2011	A-2	Production
SINIT ACM 1.1	10/2011	A-2	Production




# Intel® Xeon® Processor E7-8800/ 4800/2800 Product Families BIOS ACM Errata Summary

---

Intel Xeon Processor E7-8800/4800/2800 Product Families BIOS ACM Errata Table

Number	Release		Status	Description
	1.0	1.1		
AC1	X		Fixed	BIOS ACM Exit INIT (LockConfig) Call May Fail on Certain IOH Bus Configurations




# Intel Xeon Processor E7-8800/ 4800/2800 Product Families SINIT ACM Errata Summary

---

Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Errata Table

Number	Release		Status	Description
	1.0	1.1		
AS1	X	X	No Fix	TXT.ERRORCODE TPM command return code and launch control policy list index and minor code are not reported correctly
AS2	X		Fixed	<a href="#">SINIT Buffer Overflow Vulnerability</a>



# Errata

---

## **BP1. Intel® Interconnect BIST (Intel® IBIST) Does Not Work in Intel® QuickPath Interconnect (Intel® QPI) in Slow Mode**

**Problem:** The Intel IBIST (Interconnect Built-in Self Test) does not work in the Intel® QuickPath Interconnect (Intel® QPI) slow mode and only works at operational speed.

**Implication:** The Intel IBIST does not work in Intel QPI slow mode.

**Workaround:** Do not run the Intel IBIST in slow mode.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP2. Retraining Parameter Negotiation is Not Implemented for Intel QPI**

**Problem:** The Intel QPI specification states that the physical layer initialization process needs to negotiate retraining parameters with a remote agent. The protocol is that agents should first exchange their respective retraining interval and duration as part of the link initialization flow. Then, each agent should compare the local and remote values and choose common values by selecting the shortest interval and the longest duration. This erratum is conveying that the described negotiation feature is not implemented in the processor.

**Implication:** The processor does not perform the hardware based retraining parameter negotiation.

**Workaround:** BIOS will need to perform the necessary computations to determine the proper parameters and program them into the processor.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP3. Intel® IBIST Slave Ignores Loop Count Values Sent by Master on Intel® QPI**

**Problem:** During Intel IBIST (Interconnect Built-in Self Test) loopback, one agent is the master agent while the other is the slave agent on Intel QPI. The slave should extract an Intel IBIST loop count from the training sequence sent by the master, and use this count to time its stay in the Loopck.Pattern state before returning to Loopck.Marker state. While the processor is operating as a slave, it does not extract this loop count and times its stay in the Loopck.Pattern state based on its locally programmed loop count.

**Implication:** When operating as an Intel IBIST slave, the processor ignores the loop count values sent by the master.

**Workaround:** Software needs to program the same loop count into the master and the slave.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP4. System Hangs when Skipping Stop Req2 and Start Req1 Messages in Quiesce/Lock Sequence**

**Problem:** Quiesce master skipping the StopReq2 and the StartReq1 Intel QPI messages in the lock sequence will result in a system hang.

**Implication:** Due to this erratum, quiesce master lock flows with no StopReq2 and StartReq1 messages will cause a system hang.

**Workaround:** StopReq2 and StartReq1 messages should not be considered optional by quiesce master and must be sent to the processor as part of any lock flow.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **BP5. Integrated Memory Controller Signals Spurious CMCI when Home Agent Failover Count Saturation Occurs**

**Problem:** When home agent failover count saturation occurs, the memory controller signals a spurious CMCI (Corrected Machine Check Interrupt) without logging an error. Failover count saturation is not an error and a CMCI should not be issued.

**Implication:** Due to this erratum, software receives a CMCI with no error logged.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **BP6. Memory Controller Does Not Set S Bit for Uncorrectable Error Followed by Software Recoverable Error**

**Problem:** If an uncorrectable memory controller error is followed by a software recoverable error, the memory controller will not set the S (Signaling flag) bit of the MCI\_STATUS to indicate that a software recoverable error occurred.

**Implication:** Due to this erratum, the MCI\_STATUS of the memory controller will have the fields Valid=1, UC=1, PCC=0, OVER=1 and S=0 logged. When the MCA handler comes in, it ignores the MCI\_STATUS since S=0; and the MCA is treated as a spurious MCA.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

#### **BP7. MCI\_STATUS S Bit Not Set for LLC Software Recoverable Errors**

**Problem:** When an explicit LLC (Last Level Cache) write-back software recoverable error is detected while there is already a poison error in the MCI\_STATUS register, a machine check is signaled but the MCI\_STATUS.S (Signaling Flag) bit is not set. In this case the MCI\_STATUS.PCC (Processor Context Corrupt) bit and the S bit are both 0. As a result, the machine check handler assumes this to be a spurious error.

**Implication:** If there is already a poison error in the MCI\_STATUS register and an LLC recoverable error is then logged the MCA handler may assume this to be a spurious error.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).


#### **BP8. Correctable SB CRC Error May be Propagated to an Uncorrected ECC Error**

**Problem:** Due to the processor not having a mechanism to detect incorrect alert frames, correctable SB (South Bound) CRC Error may be propagated to an uncorrected ECC error.

**Implication:** An incorrect alert frame will not be detected by the processor. In most cases there is no issue, due to the memory buffer issuing a series of alert frames. In a specific case where a SB Intel® Scalable Memory Interconnect (Intel® SMI) CRC error (transient or persistent) is detected and the NB (North Bound) Alert frame responding to this error is also corrupted by an error, the original packet may not be reissued. However, since the memory controller uses two Intel SMI channels in lockstep for each cache line access, on a future read if one channel was affected by this issue the other would return valid data. Due to this erratum, the correctable SB CRC error may get propagated to be a detected but uncorrected ECC error. Intel has not observed this erratum on any commercially available system.

**Workaround:** None identified.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



**BP9. Memory Controller Patrol Scrub Ceases to Function with CRC Errors and the IMT31 Reclaim Feature Enabled**

**Problem:** The processor does not fully implement the protocol in the Memory Controller-Home Agent for sharing the IMT31 (In-flight Memory Table) entry resulting in a patrol scrub deadlock. This issue can occur whenever the Error Flow State is invoked in response to CRC errors or hardware injected periodic ZQCAL (ZQ Calibration).

**Implication:** Patrol scrub may not function with CRC errors and the IMT31 reclaim feature enabled.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**BP10. Electrically Idle Intel SMI and Intel QPI Lanes May Deliver Data that May Look Like Deskew Headers**

**Problem:** Intel SMI or Intel QPI lanes that are not physically connected on the board, or have become unconnected, may result in a deskew failure. A deskew failure or environmental issue may lead to Intel SMI link transitioning into a Lane Failover Mode.

**Implication:** Improper deskew headers may be observed if the Intel SMI lane of a port is not physically connected. The Intel SMI link may transition into Lane Fail-over mode.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**BP11. A Sequence of Instruction Fetches and Snoops to Locked Cache Lines May Cause Processor to Hang**

**Problem:** During a sequence of instruction fetches with specific address relationships to other system traffic a snoop beat pattern that includes snoops to locked cache lines may become established which could cause the processor to hang.

**Implication:** The processor may hang under a set of conditions involving instruction fetches, and snoops to locked cache lines.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**BP12. Writing to Unimplemented Bits of UU\_CR\_U\_MSR\_PMON\_EVNT\_SEL MSR does Not Result in #GP Fault**

**Problem:** The bits [31:23,17,15:8] in UU\_CR\_U\_MSR\_PMON\_EVNT\_SEL MSR (C10H) are not implemented on the processor and are marked as reserved. Due to this erratum writing 1's to these bits does not generate a #GP (General Protection Fault) as expected.

**Implication:** Writing 1's to the unimplemented bits in UU\_CR\_U\_MSR\_PMON\_EVNT\_SEL MSR does not result in a #GP fault.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**BP13. Mixed Rank Size Memory Configurations May Cause a Missing Refresh Event**

**Problem:** When using DIMMs of different rank sizes on the same memory channel, a refresh may be missed when a write command to a memory rank is blocked by sustained reads to another memory rank. This erratum has been seen only in a synthetic testing environment. Intel has not observed this erratum with any commercially available software.

**Implication:** A missing refresh may cause the refresh rate to be lower than the programmed value.



**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **BP14. Mirror Slave May Deliver Incorrect Data when a Read to the Mirror Master Completes Before the Write-back from the IOH**

**Problem:** A read from the mirror master may complete before the write-back from the IOH completes. This will result in the IOH write-data not being immediately visible and can lead to the IOH write-data never becoming visible. In the case of a RdInvOwn transaction, the reading caching agent will take ownership which can then overwrite the IOH data. This is especially visible in false-sharing of cache lines which involve the IOH.

**Implication:** Due to this erratum, correct data is not delivered by the mirror slave. This erratum only occurs during mirror failover.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **BP15. UU\_CR\_U\_MSR\_PMON\_GLOL\_OVF\_CTL MSR Does Not Follow RW1C Access Method**

**Problem:** The UU\_CR\_U\_MSR\_PMON\_GLOL\_OVF\_CTL MSR (C02H) is access type RW1C (Read Write 1 Clear) and when written with 1's should clear the corresponding bit in the UU\_CR\_U\_MSR\_PMON\_GLOL\_STATUS MSR (C01H). Due to this erratum, a read of the UU\_CR\_U\_MSR\_PMON\_GLOL\_OVF\_CTL MSR does not return zeros however a read of the UU\_CR\_U\_MSR\_PMON\_GLOL\_STATUS MSR will show appropriate clearing.

**Implication:** The UU\_CR\_U\_MSR\_PMON\_GLOL\_OVF\_CTL MSR does not return zeros on a read.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **BP16. HNID Field is Incorrect for CMP Messages From PrefetchHint**

**Problem:** The HNID (Home Node ID) field used in the PMON (Performance Monitoring) match/mask is incorrect for CMP (complete) messages from PrefetchHint. The same incorrect HNID is logged in the event of an error condition on a CMP for a PrefetchHint in the caching agent. The logging of the RNID (Requester Node ID) in the error logs for NDR (Non Data Response) messages is incorrect and impacts the caching agent system bound errors.

**Implication:** There are two implications:

1. Incorrect HNID is filtered or matched for CMP's using the caching agent PMON match/mask.
2. The incorrect RNID will be logged only for errors on NDR messages.

**Workaround:** There are two potential workarounds:

1. The Intel QPI performance monitor match/mask can be used to count different types of CMP messages from the caching agent.
2. Ignore the RNID field for NDR system bound messages.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **BP17. Page Fault May Occur When Logical Processor Transitions From C6 State to C0 State**

**Problem:** An unexpected Page Fault may occur when a logical processor transitions from C6 to C0, with IA-32e mode enabled.



**Implication:** Due to this erratum, an unexpected Page Fault may occur during stress testing when the processor core transitions from C6 to C0.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP18. In DAS Enabled Mode a System Hang May Occur During Memory Intensive Workloads**

**Problem:** DAS (Directory Assisted Snoopy) enabled systems may hang with home agent IMT (In-Flight Memory Table) state transition error during stress test.

**Implication:** This erratum results in home agent timeout or IMT state transition/IMT parity error causing a system hang.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Workaround:** A BIOS workaround has been identified. Please refer to reference code version 2.0 or later and release notes.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP19. Bit [8] of IA32\_APIC\_BASE register Inadvertently Set to 1 for Core 9**

**Problem:** The processor reset flow incorrectly sets BSP bit [8] to 1 in the IA32\_APIC\_BASE register for Core 9 (of 10 cores).

**Implication:** When BIOS wakes up Application Processors (APs) using INIT-SIPI-SIPI, BIOS may identify more than one Boot Strap Processor (BSP). This may lead to unpredictable system behavior.

**Workaround:** Clear bit [8] in the IA32\_APIC\_BASE register prior to the BIOS MP Initialization routine.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP20. Quad Rank DIMMs With CKE Low Enabled in Open/Adaptive Page Mode May Return Incorrect Data**

**Problem:** Memory reads may return incorrect data with CKE (Clock Enabled) Low enabled while running with homogeneous Quad Rank DIMMs in Open Page or Adaptive Page Mode.

**Implication:** System memory may return incorrect data in this configuration.

**Workaround:** Disable CKE Low if supporting Quad Rank DIMMs in Open or Adaptive Page Mode.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP21. System Configuration Controller Misaligned Error May Result in a System Hang**

**Problem:** Under certain conditions the system configuration controller may not correctly handle NcRd (Non-Coherent Read) packets which may result in a misaligned uncorrectable error, Machine Check Exception or system hang

**Implication:** The system configuration controller incorrectly signals an uncorrectable error resulting in a system hang.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP22. Recoverable Errors Signaled From Intel QPI or Intel SMI Port to the System Configuration Controller May Get Lost if the Ports are Disabled**

**Problem:** Each Intel QPI and Intel SMI physical layer port may be configured through its PBOXERRMASK register (Device:0x14, Function:0x2, Offset:0x68) to generate RAS recoverable error signals in any of the four situations: initialization failure, width reduction (Intel QPI) or lane failover (Intel SMI), drift buffer alarm, or latency buffer



roll-over. When generated, the error signal is sent to the system configuration controller where it is processed into a system management interrupt (SMI).

Under specific conditions, a RAS recoverable error signal is generated and logged in a physical layer port, but the interrupt is not generated. More specifically, the error signal is lost on the way from the port to the system configuration controller.

The problem arises when the error signal passes through a port that has been disabled. Each physical layer port has its own internal clock generator. When a port is disabled, its clock generator is off, and the error signal cannot propagate through that port.

**Implication:** If any physical layer ports are configured to signal errors of the RAS recoverable type, then depending on the pattern of disabled ports, the errors may be logged properly in the physical layer port, but a matching system management interrupt may not occur. Fatal error signals are not affected; they will always be transmitted successfully.

**Workaround:** Do not disable physical layer ports, or if they have been disabled then re-enable them, such that ports that may generate RAS recoverable errors have paths to send their error signals to the system configuration controller.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP23. Executing The WAKEUP Leaf of The GETSEC Instruction Multiple Times May Lead to a Machine Check Error**

**Problem:** The GETSEC WAKEUP leaf broadcasts a wakeup message to all logical processors currently in a SENTER sleep state. It is sufficient to execute this instruction leaf once, per MLE (Measured Launch Event) launch, by the ILP (Initiating Logical Processor). Executing the leaf multiple times may lead to buffer entry corruptions resulting in machine check errors.

**Implication:** MLE launch may hang when GETSEC WAKEUP leaf is executed multiple times during the same launch.

**Workaround:** MLE launch software can workaround this erratum by avoiding multiple GETSEC WAKEUP leaf instruction executions.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP24. CKE-Lo Feature Can Not be Disabled When Memory Controller Transactions are Active**

**Problem:** If the CKE-Lo (Clock Enable de-asserted) feature is disabled when the memory controller transactions are active, then it may cause the system to hang.

**Implication:** Disabling the CKE-Lo feature when the memory controller transactions are active, may result in the transactions timing out causing the system to hang.

**Workaround:** Software is required to quiesce memory traffic (including patrol scrub) before disabling the CKE-Lo feature.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

### **BP25. Executing The Intel TXT GETSEC SENTER Instruction Leaf May Lead to a Machine Check Error**

**Problem:** The GETSEC SENTER instruction leaf broadcasts a message in order to handshake/ rendezvous between different logical processors. The processor uses incorrect byte-enables when broadcasting this message to remote processor sockets. This may result in a Machine Check error on multi-socket platforms.

**Implication:** Due to this erratum, Intel TXT AC Modules cannot be run on multi-socket platforms.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



## **BP26. Task Switch to a TSS With an Inaccessible LDTR Descriptor May Cause Unexpected Faults**

**Problem:** A task switch may load the LDTR (Local Descriptor Table Register) with an incorrect segment descriptor if the LDT (Local Descriptor Table) segment selector in the new TSS specifies an inaccessible location in the GDT (Global Descriptor Table).

**Implication:** Future accesses to the LDT may result in unpredictable system behavior.

**Workaround:** Operating system code should ensure that segment selectors used during task switches to the GDT specify offsets within the limit of the GDT and that the GDT is fully paged into memory.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP27. An Intel QPI Link Layer Retry Quickly Followed by an Intel QPI Physical Layer Reset May Cause an MCE**

**Problem:** While an Intel QPI link is processing a link level retry requested by a remote Intel QPI agent (due to link CRC errors), if an Intel QPI phy layer reset is triggered and aligns with a specific retry stage, a packet may get dropped and cause time out error with MCA error code, IA32\_MCi\_Status [15:0] encoded as a Bus and Interconnect Error with Timeout [bit 8] = 1, Cache Hierarchy Error, or Internal Timer error.

**Implication:** Due to this erratum, a fatal MCE may be signaled with MCA error code, IA32\_MCi\_Status [15:0] encoded as a Bus and Interconnect Error with Timeout [bit 8] = 1, Cache Hierarchy Error, or Internal Timer error.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP28. LLC Arrays May have Incorrect Values after Warm Reset when Memory BIST is Disabled**

**Problem:** When Memory BIST is disabled in the platform, LLC (Last Level Cache) arrays do not get initialized properly when coming out of warm reset.

**Implication:** Due to this erratum, data may be left valid in the LLC array which subsequently may be used/consumed by the processor during BIOS execution leading to unpredictable system behavior

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP29. VM Entries that Return from SMM May Incorrectly Write to the SMRR Protected Region**

**Problem:** If the executive-VMCS pointer field in the VMCS does not contain the VMXON pointer and the "use TPR shadow" VM-execution control is 1 in the executive VMCS, a VM entry that returns from SMM may write to the virtual-APIC page. Due to this erratum, this write may occur even if the virtual-APIC page is in the region protected by the SMRR (system-management range register).

**Implication:** The writes to the virtual-APIC page may corrupt data in SMRAM.

**Workaround:** If software sets the "use TPR shadow" VM-execution control to 1, it should not VMWRITE the virtual-APIC address to an address in the range protected by the SMRR.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **BP30. System Quiesce Events Initiated While Power Events are In Progress May Cause System Hangs**

**Problem:** BIOS initiation of a system quiesce flow via the QUIESCE\_CONTROL2 MSR (51H) and exit of a system quiesce flow QUIESCE\_CONTROL1 MSR (50H) via may conflict with a power event on the BSP (Boot Strap Processor) core. Due to this conflict, the BSP core,



which BIOS code runs on, may have one thread take the power event and the other thread not take the power event, resulting in a system hang.

**Implication:** As a result of this erratum, the system may hang after BIOS initiates a system quiesce flow.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP31. Uncorrected Memory Error Detected by a Memory Patrol Scrub With SMI Generated by Other Memory Controllers May Cause MCE/System Management Interrupt Race Condition**

**Problem:** BIOS may configure a System Management Interrupt to be signaled when the patrol scrub engine has reached the end of scrubbing a memory range. If the System Management Interrupt is generated while an uncorrected error is detected by another memory patrol scrub engine, it may result MCE/SMI race condition which may lead to system shut down.

**Implication:** Due to this erratum, the system may shut down.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP32. Broken trace to either the P or the N lane of the Intel SMI forwarded clock differential pair may result in loss of forwarded clock but not always lead to clock lane failover.**

**Problem:** If either only the P or the N lane of the Intel SMI forwarded clock is broken, then processor is capable of detecting minimum differential swing on the clock lane, thus resulting in the processor to assume that the forwarded clock still exists. Consequently, the processor will proceed to the Intel SMI link training phase.

**Implication:** If the processor proceeds to the link training phase, then based on observations, it is possible that the Intel SMI link may fail to train even after seven retry attempts and continue to remain in RESET state; or, if the link successfully reached LO state, then the link may be unstable and shortly return to Disable\_a state. However, if the P and N lanes of the forwarded clock differential pair are both broken due to board trace issues, then the clock failover mechanism on Intel SMI channel has been found to operate successfully as expected.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP33. Package C3/C6 with Memory Self-refresh Enabled May Cause False Error Logging**

**Problem:** When the processor is in Package C3/C6 with Memory Self Refresh, correctable errors may occur resulting in a SMI (system management interrupt). The SMI generation may result in a false error being logged in the IA32\_MC6\_STATUS (MSR 0x419) register.


**Implication:** Due to this erratum, a false error may be reported in IA32\_MC6\_STATUS register.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP34. Performance Monitor WOKEN Event May Under Count**

**Problem:** Performance Monitoring counter WOKEN (Event: 0x0F8) counts the number of cores woken up from core C-states. Due to this erratum, the WOKEN event may not count



the cores that are woken up from core C-states due to Trusted Execution Technology transactions.

**Implication:** Performance Monitoring Event WOKEN will under count the number of cores woken up from core C-states due to Trusted Execution Technology transaction.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP35. PECCI Command Average Temperature Read does not report correct Temperature**

**Problem:** The PECCI (Platform Environment Control Interface) mailbox command 0x21, Average Temperature Read, is a feature which calculates the average temperature of the processor cores and reports it. In some instances the temperature reported out from the PECCI Command Average Temperature Read is significantly higher than the actual processor average temperature.

**Implication:** The PECCI Command Average Temperature Read may report a temperature that is higher than the actual processor average temperature.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP36. QPI Initialization May Cause a CATERR During Power-on Reset**

**Problem:** In a complex set of circumstances during a power cycle reset, a CATERR may occur during the QPI initialization sequence as a result of a race condition where a QPI completion transaction arrives while the receiver is still going through its initialization.

**Implication:** One of the application processors PBSP (package BSP) may cause a CATERR assertion resulting in a failure to complete BIOS post. This is only a boot issue and cannot occur during run-time.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP37. EOI Transaction May Not be Sent if Software Enters Core C6 During an Interrupt Service Routine**

**Problem:** If core C6 is entered after the start of an interrupt service routine but before a write to the APIC EOI (End of Interrupt) register, and the core is woken up by an event other than a fixed interrupt source the core may drop the EOI transaction the next time APIC EOI register is written and further interrupts from the same or lower priority level will be blocked.

**Implication:** EOI transactions may be lost and interrupts may be blocked when core C6 is used during interrupt service routines.

**Workaround:** Software should check the ISR register and if any interrupts are in service only enter C1.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **BP38. A First Level Data Cache Parity Error May Result in Unexpected Behavior**

**Problem:** When a load occurs to a first level data cache line resulting in a parity error in close proximity to other software accesses to the same cache line and other locked accesses the processor may exhibit unexpected behavior.

**Implication:** Due to this erratum unpredictable system behavior may occur. Intel has not observed this erratum with any commercially available system.

**Workaround:** None identified.



Status: For the steppings affected, see the [Summary Tables of Changes](#).

### **BP39. An Unexpected Page Fault or EPT Violation May Occur After Another Logical Processor Creates a Valid Translation for a Page**

**Problem:** An unexpected page fault (#PF) or EPT violation may occur for a page under the following conditions:

- The paging structures initially specify no valid translation for the page.
- Software on one logical processor modifies the paging structures so that there is a valid translation for the page (e.g., by setting to 1 the present bit in one of the paging-structure entries used to translate the page).
- Software on another logical processor observes this modification (e.g., by accessing a linear address on the page or by reading the modified paging-structure entry and seeing value 1 for the present bit).
- Shortly thereafter, software on that other logical processor performs a store to a linear address on the page.

In this case, the store may cause a page fault or EPT violation that indicates that there is no translation for the page (e.g., with bit 0 clear in the page-fault error code, indicating that the fault was caused by a not-present page). Intel has not observed this erratum with any commercially available software.

**Implication:** An unexpected page fault may be reported. There are no other side effects due to this erratum.

**Workaround:** System software can be constructed to tolerate these unexpected page faults. See Section "Propagation of Paging-Structure Changes to Multiple Processors" of Volume 3A of the IA-32 Intel® Architecture Software Developer's Manual, for recommendations for software treatment of asynchronous paging-structure updates.

Status: For the steppings affected, see the [Summary Tables of Changes](#).

### **BP40. A Page Fault May Not be Generated When the PS bit is set to "1" in a PML4E or PDPTE**

**Problem:** On processors supporting Intel® 64 architecture, the PS bit (Page Size, bit 7) is reserved in PML4Es and PDPTEs. If the translation of the linear address of a memory access encounters a PML4E or a PDPTE with PS set to 1, a page fault should occur. Due to this erratum, PS of such an entry is ignored and no page fault will occur due to its being set.

**Implication:** Software may not operate properly if it relies on the processor to deliver page faults when reserved bits are set in paging-structure entries.


**Workaround:** Software should not set bit 7 in any PML4E or PDPTE that has Present Bit (Bit 0) set to "1".

Status: For the steppings affected, see the [Summary Tables of Changes](#).

### **BP41. IO\_SMI Indication in SMRAM State Save Area May be Set Incorrectly**

**Problem:** The IO\_SMI bit in SMRAM's location 7FA4H is set to "1" by the processor to indicate a System Management Interrupt (SMI) occurred as the result of executing an instruction that reads from an I/O port. Due to this erratum, the IO\_SMI bit may be incorrectly set by:

- A non-I/O instruction
- An event where an I/O read sets the IO\_SMI bit but another interrupt is taken before the recognition of the SMI event
- A REP INS instruction
- A I/O read that redirects to MWAIT



**Implication:** SMM handlers may get false IO\_SMI indication.

**Workaround:** The SMM handler has to evaluate the saved context to determine if the SMI was triggered by an instruction that read from an I/O port. The SMM handler must not restart an I/O instruction if the platform has not been configured to generate a synchronous SMI for the recorded I/O port address.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).

**BP42. Writing an Illegal Vector to the IA32\_X2APIC\_SELF\_IPI MSR Will Hang the Processor**

**Problem:** Writing an illegal vector (0 to 15) to the IA32\_X2APIC\_SELF\_IPI MSR while the local APIC is in x2APIC mode will cause the processor to hang.

**Implication:** When this erratum occurs, the processor will hang.

**Workaround:** Software should not write an illegal vector to the IA32\_X2APIC\_SELF\_IPI MSR while the local APIC is in X2APIC mode. Virtual-machine monitors should not allow guest software to write to the IA32\_X2APIC\_SELF\_IPI MSR.

**Status:** For the steppings affected, see the [Summary Tables of Changes](#).



# Intel Xeon Processor E7-8800/ 4800/2800 Product Families BIOS ACM Errata

---


## **AC1. BIOS ACM Exit INIT (LockConfig) Call May Fail on Certain IOH Bus Configurations**

**Problem:** With certain IOH bus configurations, the BIOS ACM Exit Init (LockConfig) call may be unable to lock the IOHs and the call will fail.

**Implication:** When this erratum occurs, the TXT.HEAP.BASE and TXT.HEAP.SIZE registers will be locked, and BIOS will be unable to setup TXT heap memory for MLE (Measured Launch Environment) boot.

**Workaround:** On single IOH configurations, the IOH can use bus 0x00-0x7F to avoid this erratum. On dual IOH configurations, IOH0 can use bus 00-0x7F and IOH1 can use bus 0x80-0xF7 to avoid this erratum.

**Status:** Fixed in BIOS ACM 1.1.



# Intel Xeon Processor E7-8800/ 4800/2800 Product Families SINIT ACM Errata

---

## **AS1. TXT.ERRORCODE TPM Command Return Code And Launch Control Policy List Index And Minor Code Are Not Reported Correctly.**

**Problem:** On affected SINIT ACM releases, the TXT.ERRORCODE register TPM command return code (bits 24:16), Launch Control Policy List Index (bits 24:22) and Launch Control Policy Minor Code (bits 21:16) are not reported correctly.

**Implication:** Software depending upon TXT.ERRORCODE error reporting for the TPM command return code, Launch Control Policy List Index, or Launch Control Policy Minor Code may not behave as expected.

**Workaround:** None.

**Status:** See [Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Errata](#) for affected releases.


## **AS2. SINIT Buffer Overflow Vulnerability**

**Problem:** SINIT Authenticated Code Module (ACM) 1.0 is susceptible to a buffer overflow issue.

**Implication:** When Intel® Trusted Execution Technology measured launch is invoked using SINIT Authenticated Code Module 1.0, the platform is susceptible to an OS kernel-level exploit which may compromise certain SINIT ACM functionality.

**Workaround:** It is possible for a BIOS update and an updated SINIT ACM 1.1 to be used as a workaround for this erratum. Previous SINIT ACM releases will no longer function with the BIOS update.

**Status:** See [Intel Xeon Processor E7-8800/4800/2800 Product Families SINIT ACM Errata](#) for affected releases.




## Specification Changes

---

The Specification Changes listed in this section apply to the following documents:

- *Intel® Xeon® Processor E7-8800/4800/2800 Product Families Datasheet, Volumes 1 and 2*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

There are no new Specification Changes in this Specification Update revision.



# Specification Clarifications

---

The Specification Clarifications listed in this section may apply to the following documents:

- *Intel® Xeon® Processor E7-8800/4800/2800 Product Families Datasheet, Volumes 1 and 2*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

There are no new Specification Clarifications in this Specification Update revision.



## Documentation Changes

---

The Documentation Changes listed in this section apply to the following documents:

- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide*
- *Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide*

All Documentation Changes will be incorporated into a future version of the appropriate Processor documentation.

**Note:**

Documentation changes for *Intel® 64 and IA-32 Architecture Software Developer's Manual* volumes 1, 2A, 2B, 3A, and 3B will be posted in a separate document, *Intel® 64 and IA-32 Architecture Software Developer's Manual Documentation Changes*. Follow the link below to become familiar with this file.

<http://developer.intel.com/products/processor/manuals/index.htm>

There are no new Documentation Changes in this Specification Update revision.

### §